


Chapter 11: Metal
Alloys
Applications and
Processing


ISSUES TO ADDRESS...

- How are metal alloys classified and how are they used?
- What are some of the common fabrication techniques?
- How do properties vary throughout a piece of material that has been quenched, for example?
- How can properties be modified by post heat treatment?


Definitions: Components and Phases



Steel



Refinement of Steel from Ore



Ferrous Alloys

Iron containing – Steels - cast irons

Nomenclature AISI (American Iron and Steel Institute) & SAE
(Society of Automotive Engineers)

- **10xx** Plain Carbon Steels
- **11xx** Plain Carbon Steels (resulfurized for machinability)
- **15xx** Mn (1.0 ~ 1.65%)
- **40xx** Mo (0.20 ~ 0.30%)
- **43xx** Ni (1.65 - 2.00%), Cr (0.4 - 0.90%), Mo (0.2 - 0.3%)
- **44xx** Mo (0.5%)

where xx is wt% C x 100

Example: 1060 steel – plain carbon steel with 0.60 wt% C

Stainless Steel -- >11% Cr


Cast Iron

- Ferrous alloys with > 2.1 wt % C
 - more commonly 3 - 4.5 wt % C
- low melting (also brittle) so easiest to cast
- Cementite decomposes to ferrite + graphite
$$\text{Fe}_3\text{C} \rightarrow 3 \text{Fe} (\alpha) + \text{C} (\text{graphite})$$
 - generally a slow process

Fe-C True Equilibrium Diagram

Graphite formation promoted by

- Si > 1 wt%
- slow cooling



Types of Cast Iron


Gray iron (C, Si, Fe)

- graphite flakes.
- weak & brittle under tension
- stronger under compression
- excellent vibrational dampening
- wear resistant



Ductile iron

- add Mg or Ce (Cerium)
- graphite in nodules not flakes
- matrix often pearlite - better ductility



Types of Cast Iron


White iron

- <1 wt % Si so harder but brittle
more cementite



Malleable iron

- Starts as a white iron casting then heat treated at 800-900°C
- graphite separates out slowly
- more ductile




Production of Cast Iron

Comparative qualities of cast irons^[1]

| Name | Nominal composition [% by weight] | Form and condition | Yield strength [ksi (0.2% offset)] | Tensile strength [ksi] | Elongation [% (in 2 inches)] | Hardness [Brinell scale] | Uses |
|-------------------------------------|--|------------------------|---------------------------------------|---------------------------|---------------------------------|-----------------------------|--|
| Cast grey iron (ASTM A48) | C 3.4, Si 1.8, Mn 0.5 | Cast | — | 25 | 0.5 | 180 | Engine blocks, fly-wheels, gears, machine-tool bases |
| White | C 3.4, Si 0.7, Mn 0.6 | Cast (as cast) | — | 25 | 0 | 450 | Bearing surfaces |
| Malleable iron (ASTM A47) | C 2.5, Si 1.0, Mn 0.55 | Cast (annealed) | 33 | 52 | 12 | 130 | Axle bearings, track wheels, automotive crankshafts |
| Ductile or nodular iron | C 3.4, P 0.1, Mn 0.4, Ni 1.0, Mg 0.06 | Cast | 53 | 70 | 18 | 170 | Gears, cams, crankshafts |
| Ductile or nodular iron (ASTM A339) | — | Cast (quench tempered) | 108 | 135 | 5 | 310 | — |
| Ni-hard type 2 | C 2.7, Si 0.6, Mn 0.5, Ni 4.5, Cr 2.0 | Sand-cast | — | 55 | — | 550 | Strength |
| Ni-resist type 2 | C 3.0, Si 2.0, Mn 1.0, Ni 20.0, Cr 2.5 | Cast | — | 27 | 2 | 140 | Resistance to heat and corrosion |


Production of Cast Iron



Limitations of Ferrous Alloys

- 1) Relatively high density
- 2) Relatively low conductivity
- 3) Poor corrosion resistance

Nonferrous Alloys



Metal Fabrication

1. Forming
2. Casting
3. Joining

Metal Fabrication

1. Forming Operations

- Rough stock formed to final shape

Hot working

vs.


Cold working

- T high enough for recrystallization
- Larger deformations
- well below T_m
- work hardening
- smaller deformations

Metal Fabrication Methods - I

FORMING

- Forging (Hammering; Stamping) (wrenches, crankshafts)



- Drawing (rods, wire, tubing)




die must be well lubricated & clean


CASTING

JOINING

- Rolling (Hot or Cold Rolling) (I-beams, rails, sheet & plate)




- Extrusion (rods, tubing)



ductile metals, e.g. Cu, Al (hot)

Metal Fabrication Methods - II



- **Casting**- mold is filled with metal
 - metal melted in furnace, perhaps alloying elements added. Then cast in a mold
 - most common, cheapest method
 - gives good production of shapes
 - weaker products, internal defects
 - good option for brittle materials

Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- **Sand Casting**

(large parts, e.g.,
auto engine blocks)



- trying to hold something that is hot
- what will withstand $> 1600^{\circ}\text{C}$?
- cheap - easy to mold => sand!!!
- pack sand around form (pattern) of desired shape

Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- **Sand Casting**


(large parts, e.g.,
auto engine blocks)



- **Investment Casting**

(low volume, complex shapes
e.g., jewelry, turbine blades)

plaster
die formed
around wax
prototype



Investment Casting

- pattern is made from paraffin.
- mold made by encasing in plaster of paris
- melt the wax & the hollow mold is left
- pour in metal


Metal Fabrication Methods - II

Pattern Tree

Shell-Making

Investment Casting

Casting



Copyright © 2008 CustomPartNet

Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- Sand Casting

(large parts, e.g.,
auto engine blocks)



- Investment Casting


(low volume, complex shapes
e.g., jewelry, turbine blades)

plaster
die formed
around wax
prototype



- Die Casting

(high volume, low T alloys)



- Continuous Casting


(simple slab shapes)



Metal Fabrication Methods - III

FORMING


- Powder Metallurgy
(materials w/low ductility)



CASTING

JOINING


- Welding
(when one large part is impractical)



- Heat affected zone:
(region in which the microstructure has been changed).

Thermal Processing of Metals Metal

- Annealing occurs by the **diffusion** of atoms within a solid material, so that the material progresses towards its **equilibrium state**.



Thermal Processing of Metals

- There are three stages in the annealing process:
 1. **Recovery phase**, which results in softening of the metal through removal of crystal defects.
 2. **Recrystallization**, where new strain-free grains nucleate and grow to replace those deformed by internal stresses.
 3. **Grain growth**, in which the microstructure starts to coarsen and may cause the metal to have less than satisfactory mechanical properties.

Types of Annealing

1) Normalization

- Normalization is an annealing process in which a metal is cooled in air after heating.
- It involves heating the steel to just above its upper critical point.
- It is soaked for a short period then allowed to cool in air.
- It is typically confined to hardenable steel.
- It is used to refine grains which have been deformed through cold work.
- Can improve ductility and toughness of the steel.
- Small grains are formed which give a much harder and tougher metal with normal tensile strength and not the maximum ductility achieved by annealing.

2) Process annealing


- Process annealing, also called "intermediate annealing", "subcritical annealing", or "in-process annealing", is a heat treatment cycle that restores some of the ductility to a work piece allowing it be worked further without breaking.
- Ductility is important in shaping and creating a more refined piece of work through processes such as rolling, drawing, and extruding.
- The piece is heated to a temperature typically below the austenizing temperature, and held there for long enough to relieve stresses in the metal.
- The piece is finally cooled slowly in to room temperature.
- The temperature ranges from 500 °F to 1400 °F, depending on the alloy in question.

3) Full annealing


- Full annealing is accomplished by heating a hypoeutectoid steel to a temperature above (50°C) the UCT (Upper Critical Temperature). For hypereutectoid steel the sample should be heated to a temperature above the LUC.
- It is then cooled in the furnace very slowly to room temperature.
- The formation of austenite destroys all structures that have existed before heating.
- Slow cooling yields the original phases of ferrite and pearlite.

Hardenability-Steels

- Ability to form martensite very hard form of steel crystalline structure
- Jominy end quench test to measure hardenability.




- Hardness versus distance from the quenched end.



Why Hardness Changes W/Position

- The cooling rate varies with position.



Quenching Medium & Geometry

- Effect of quenching medium:

| Medium | Severity of Quench | Hardness |
|--------|--------------------|----------|
| air | low | low |
| oil | moderate | moderate |
| water | high | high |

- Effect of geometry:

When surface-to-volume ratio increases:

--cooling rate increases

--hardness increases

