

Chapter 8

Applications and Processing of Metal Alloys


The University of Jordan
Chemical Engineering Department
Fall 2022
Prof. Yousef Mubarak

ISSUES TO ADDRESS...


- How are metal alloys classified and what are their common applications?
- What are some of the common fabrication techniques for metals?
- What heat treatment procedures are used to improve the mechanical properties of both ferrous and nonferrous alloys? (*will not be covered this semester*)



Classification of Metal Alloys




Steels



increasing strength, cost, decreasing ductility

Refinement of Steel from Ore



Ferrous Alloys

➤ *Iron-based alloys:*

- *Steel*
- *Cast Irons*

➤ *Nomenclature for steels (AISI/SAE)*

10xx *Plain Carbon Steels*

11xx *Plain Carbon Steels (resulfurized for machinability)*

15xx *Mn (1.00 - 1.65%)*

40xx *Mo (0.20 ~ 0.30%)*

43xx *Ni (1.65 - 2.00%), Cr (0.40 - 0.90%), Mo (0.20 - 0.30%)*


44xx *Mo (0.5%)*

where xx is wt% C x 100


Example: *1060 steel – plain carbon steel with 0.60 wt% C*
Stainless Steel >11% Cr

Cast Irons

- Ferrous alloys with $> 2.1 \text{ wt\% C}$
 - More commonly 3 - 4.5 wt% C
- Low melting - relatively easy to cast
- Generally brittle
- Cementite decomposes to ferrite + graphite




- This decomposition process is generally a slow process




Graphite formation promoted by:

- ✓ $\text{Si} > 1 \text{ wt\%}$
- ✓ slow cooling

Types of Cast Iron




Types of Cast Iron



Types of Cast Iron


Gray Iron

- *Graphite flakes*
- *Weak & brittle in tension*
- *Stronger in compression*
- *Excellent vibrational dampening*
- *Wear resistant*



Ductile Iron


- *Add Mg and/or Ce*
- *Graphite as nodules not flakes*
- *Matrix often pearlite – stronger but less ductile*



Types of Cast Iron


White iron

- $< 1 \text{ wt\% Si}$
- Pearlite + cementite
- Very hard and brittle



Malleable iron


- Heat treat white iron at 800-900°C
- Graphite in rosettes
- Reasonably strong and ductile



Types of Cast Iron

Compacted graphite iron



- *Can be prepared by addition of small amount of Ce or Mg to gray cast iron*
- *Relatively high thermal conductivity*
- *Good resistance to thermal shock*
- *Lower oxidation at elevated temperatures*



Production of Cast Irons

G_f = flake graphite
 G_n = graphite nodules
 G_r = graphite rosettes


Reheat White Cast Iron



Fast cool	Moderate	Slow cool
$P + \text{Fe}_3\text{C}$	$P + G_f$	$\alpha + G_f$



White cast iron




Pearlitic gray cast iron




Ferritic gray cast iron

Moderate	Slow cool
$P + G_n$	$\alpha + G_n$



Pearlitic ductile cast iron



Ferritic ductile cast iron

Limitations of Ferrous Alloys

- One main drawback of ferrous alloys is their environmental degradation i.e. *poor corrosion resistance*.
- Other disadvantages include:
 - 1) Relatively high densities.
 - 2) Relatively low electrical conductivities
 - 3) High cost to finish product
- In ferrous materials the main alloying element is carbon

Nonferrous Alloys

• Cu Alloys

Brass: Zn is subst. impurity (costume jewelry, coins, corrosion resistant)

Bronze: Sn, Al, Si, Ni are subst. impurities (bushings, landing gear)

Cu-Be:
precip. hardened for strength

• Ti Alloys

-relatively low ρ : 4.5 g/cm³

vs 7.9 for steel

-reactive at high T 's
-space applic.

• Al Alloys

-low ρ : 2.7 g/cm³

-Cu, Mg, Si, Mn, Zn additions
-solid sol. or precip.

strengthened (struct. aircraft parts & packaging)

• Mg Alloys

-very low ρ : 1.7g/cm³

-ignites easily
-aircraft, missiles

• Refractory metals

-high melting T 's
-Nb, Mo, W, Ta

NonFerrous Alloys

• Noble metals

-Ag, Au, Pt
-oxid./corr. resistant

Metal Fabrication

➤ *How do we fabricate metals?*

- *Blacksmith - hammer (forged)*
- *Cast molten metal into mold*

➤ *Forming Operations*

- *Rough stock formed to final shape*

Hot working

- ✓ *Deformation temperature high enough for recrystallization*
- ✓ *Large deformations*

vs.

Cold working

- ✓ *Deformation below recrystallization temperature*
- ✓ *Strain hardening occurs*
- ✓ *Small deformations*


Metal Fabrication Methods (i)

FORMING


CASTING

JOINING


- **Forging (Hammering; Stamping)**
(wrenches, crankshafts)




- **Drawing**
(rods, wire, tubing)



- **Rolling (Hot or Cold Rolling)**
(I-beams, rails, sheet & plate)



- **Extrusion**
(rods, tubing)



Metal Fabrication Methods (ii)



- *Casting- mold is filled with molten metal*
 - *Metal melted in furnace, perhaps alloying elements added, then cast in a mold*
 - *Common and inexpensive*
 - *Gives good production of shapes*
 - *Weaker products, internal defects*
 - *Good option for brittle materials*

Metal Fabrication Methods (ii)

FORMING

CASTING


JOINING

- *Sand Casting*
(large parts, e.g.,
auto engine blocks)

- What material will withstand $T > 1600^{\circ}\text{C}$ and is inexpensive and easy to mold?

Answer: sand!!!

- To create mold, pack sand around form (pattern) of desired shape





Metal Fabrication Methods (ii)

FORMING

CASTING


JOINING


➤ **Investment Casting** (low volume, complex shapes e.g., jewelry, turbine blades)

Stage I: Mold formed by pouring plaster of paris around wax pattern. Plaster allowed to harden.

Stage II: Wax is melted and then poured from mold—hollow mold cavity remains.

Stage III: Molten metal is poured into mold and allowed to solidify.





Metal Fabrication Methods (ii)


FORMING

CASTING

JOINING


➤ *Die Casting*


- *High volume*
- *For alloys having low melting temperatures*




➤ *Continuous Casting*

- *Simple shapes: rectangular slabs, cylinders*





Continuous Casting





Metal Fabrication Methods (ii)

FORMING

CASTING

JOINING

- *Powder Metallurgy*
(metals with low ductility)



Metal Fabrication Methods (ii)

FORMING

CASTING

JOINING

➤ *Welding*

(when fabrication of one large part is impractical)

- *Heat-affected zone:*
(region in which the microstructure has been changed).

