



University of Jordan
Chemical Engineering Department
905509 Statistical Quality Control

Control Charts for Attributes

Dr. Ali Kh. Al-Matar
aalmatar@ju.edu.jo

Outline

- What is an attribute?
- Types of control charts for attributes.
- Binomial distribution.
- Control charts for fraction nonconforming.
- Positive lower control limits.
- Variable sample size.




Attribute Data

- Data that can be classified into one of several categories or classifications is known as attribute data.
 - Classifications such as conforming and nonconforming are commonly used in quality control.
 - Another example of attributes data is the count of defects.



Attribute Control Charts



Fraction Nonconforming

- Fraction nonconforming is the ratio of the number of nonconforming items in a population to the total number of items in that population.

$$p = \frac{\text{Number of nonconforming items}}{\text{Total number of items}}$$

- Control charts for fraction nonconforming are based on the binomial distribution.



Binomial Distribution

- A quality characteristic follows a binomial distribution if the following are met:
 1. All trials are independent.
 2. Each outcome is either a “success” or “failure”.
 3. The probability of success on any trial is given as p , the probability of a failure is $1-p$.
 4. The probability of a success is constant.



Binomial Distribution Mathematics

- The binomial distribution with parameters $n > 0$ and $0 < p < 1$, is given by

$$p(x) = \binom{n}{x} p^x (1-p)^{n-x}$$

- Mean of the binomial distribution

$$\mu = np$$

- Standard deviation of the binomial distribution

$$\sigma^2 = np(1-p)$$



Notation for Fraction Nonconforming Charts

- n = number of units of product selected at random.
- D = number of nonconforming units from the sample
- p = probability of selecting a nonconforming unit from the sample.
- Then

$$P(D = x) = \binom{n}{x} p^x (1-p)^{n-x}$$



Sample Fraction Nonconforming

- The sample fraction nonconforming is given as

$$\hat{p} = \frac{D}{n}$$

- where \hat{p} is a random variable with mean and variance

$$\mu = p \quad \sigma^2 = \frac{p(1-p)}{n}$$



Control limits for Fraction Nonconforming

- Standard value of p given

$$\begin{aligned} UCL &= p + 3\sqrt{\frac{p(1-p)}{n}} \\ CL &= p \\ LCL &= p - 3\sqrt{\frac{p(1-p)}{n}} \end{aligned}$$

- Standard value of p not given

$$\begin{aligned} UCL &= \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \\ CL &= \bar{p} \\ LCL &= \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \\ \bar{p} &= \frac{\sum_{i=1}^m D_i}{mn} = \frac{\sum_{i=1}^m \hat{p}_i}{m} \end{aligned}$$



Trial Control Limits


- Control limits that are based on a preliminary set of data can often be referred to as trial control limits.
- The quality characteristic is plotted against the trial limits, **if any points plot out of control, assignable causes** should be investigated and **points removed**.
- With removal of the points, the limits are then recalculated.



Example

- A process that produces bearing housings is investigated. Ten samples of size 100 are selected. The data are given below, is the process in statistical control?

Sample #	1	2	3	4	5	6	7	8	9	10
Number nonconforming	5	2	3	8	4	1	2	6	3	4



Sample Size

- The sample size can be determined so that a shift of some specified amount, δ can be detected with a stated level of probability
- Duncan (1986) suggests being able to detect a process shift with a 50% chance.

$$\delta = L \sqrt{\frac{p(1-p)}{n}}$$

$$n = \left(\frac{L}{\delta}\right)^2 p(1-p)$$



- Probability of a defect occurring is $p=0.01$. Probability of a defect occurring after a process shift is $p=0.05$. What would be an appropriate sample size to detect this shift?

$$\delta = 0.05 - 0.01 = 0.04$$

$$n = \left(\frac{L}{\delta}\right)^2 p(1-p)$$

$$n = \left(\frac{3}{0.04}\right)^2 (0.01)(1 - 0.01) = 56$$



Positive LCL

- The sample size n , can be chosen so that the lower control limit would be nonzero:

$$LCL = p - L\sqrt{\frac{p(1-p)}{n}} > 0$$

$$n > \frac{(1-p)}{p} L^2$$



np Control Charts

- The number of nonconforming can be plotted instead of the fraction nonconforming.

$$UCL = np + 3\sqrt{np(1-p)}$$

$$CL = np$$

$$LCL = np - 3\sqrt{np(1-p)}$$

- If a standard p is not given use the sample estimate of p .



Points Below LCL

- Care must be exercised in interpreting points that plot below the lower control limit.
 - They often do not indicate a real improvement in process quality.
 - They are frequently caused by errors in the inspection process or improperly calibrated test and inspection equipment.



Variable Sample Size

- Suppose you want to do 100% inspection of the process output over some period of time.
- Since different numbers of units could be produced in each period, the control chart would then have a variable sample size.
- Three approaches can be used
 - Variable width control limits.
 - Control limits based on average sample Size.
 - Standardized Control Chart.



Variable Width Control Limits

- Determine control limits for each individual sample that are based on the specific sample size.
- Upper and Lower control limits are given by

$$UCL = p + 3\sqrt{\frac{p(1-p)}{n_i}}$$

$$LCL = p - 3\sqrt{\frac{p(1-p)}{n_i}}$$




Figure 6-6 Control chart for fraction nonconforming with variable sample size.



Control Limits Based on Average Sample Size

- Control charts based on the average sample size results in an approximate set of control limits.

- Average sample size is given by

$$\bar{n} = \frac{\sum_{i=1}^m n_i}{m}$$

- Upper and lower control limits are given by

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{\bar{n}}}$$

$$LCL = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{\bar{n}}}$$






Figure 6-8 Control chart for fraction nonconforming based on average sample size.



Standardized Control Chart

- The points plotted are in terms of standard deviation units.
- The standardized control chart has the following properties:
 - Center line at 0 (zero).
 - UCL at 3.
 - LCL at -3.
- The points plotted are given by:

$$z_i = \frac{\hat{p}_i - p}{\sqrt{p(1-p)/n_i}}$$






Figure 6-9 Standardized control chart for fraction nonconforming.



SQC-08: Attributes Control charts

©Dr. Ali Khalaf Al-Matar, aalmatar@ju.edu.jo

23



Control Charts for Nonconformities (Defects)

Control Charts for Nonconformities (Defects)

- There are many instances where an item will contain nonconformities but the item itself is not classified as nonconforming.
- It is often important to construct control charts for:
 - total number of nonconformities (c -chart) for an inspection unit, or
 - average number of nonconformities (\bar{u} -chart) for a given “area of opportunity” per inspection unit.
- The inspection unit must be the same for each unit e.g., per unit time, per lot, per cubic meter etc.



Poisson Distribution

- The number of nonconformities in a given area can be modeled by the Poisson distribution.
 - Number of locations for nonconformities are large.
 - Probability of occurrence of a nonconformity at any location is small.
 - In other words, can have large probability of occurring anywhere, but small probability of occurring in the same place.
- Let c ($c > 0$) be the parameter for a Poisson distribution (average number of nonconformities), then the mean and variance of the Poisson distribution are equal to the value c .
- The probability of obtaining x nonconformities on a single inspection unit, when the average number of nonconformities is some constant, c , is found using:

$$p(x) = \frac{e^{-c} c^x}{x!}$$



c-Chart for Constant Sample Size

- Standard value of c given

$$\begin{aligned}UCL &= c + 3\sqrt{c} \\ CL &= c \\ LCL &= c - 3\sqrt{c}\end{aligned}$$

- Standard value of c not given

$$\begin{aligned}UCL &= \bar{c} + 3\sqrt{\bar{c}} \\ CL &= \bar{c} \\ LCL &= \bar{c} - 3\sqrt{\bar{c}}\end{aligned}$$

Control chart for nonconformities with sample size = 1 inspection unit



Choice of Sample Size (u-Chart)

- If we find c total nonconformities in a sample of n inspection units, then the average number of nonconformities per inspection unit is

$$u = \frac{c}{n}$$

- The control limits for the average number of nonconformities is

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{n}}$$

$$CL = \bar{u}$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{n}}$$

Control chart for nonconformities with sample size = n inspection unit



Variable Sample Size

- Three approaches can be used
 - Variable width control limits.
 - Control limits based on average sample Size.
 - Standardized Control Chart.



Variable Width Control Limits

- Determine control limits for each individual sample that are based on the specific sample size.
- Upper and Lower control limits are given by

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{n_i}}$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{n_i}}$$



Control Limits Based on Average Sample Size

- Control charts based on the average sample size results in an approximate set of control limits.

- Average sample size is given by

$$\bar{n} = \frac{\sum_{i=1}^m n_i}{m}$$

- Upper and lower control limits are given by

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{\bar{n}}}$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{\bar{n}}}$$



Standardized Control Chart

- The points plotted are in terms of standard deviation units.
- The standardized control chart has the following properties:
 - Center line at 0 (zero).
 - UCL at 3.
 - LCL at -3.
- The points plotted are given by:

$$z_i = \frac{u_i - \bar{u}}{\sqrt{\bar{u} / n_i}}$$




Demerit System

■ Demerit System

- A system for classifying several less severe or minor defects.
- Classify defects according to severity.
- Provides a reasonable framework for weighting various types of defects



Demerit System Classification of Defects



Number of Demerits

- Let c_{iA} , c_{iB} , c_{iC} , and c_{iD} represent the number of units in each of the four classes.
- The number of demerits in an inspection unit (d_i) is given by

$$d_i = 100c_{iA} + 50c_{iB} + 10c_{iC} + c_{iD}$$

- Number of demerits per unit (n is number of inspection units)

$$u_i = \frac{\sum_{i=1}^n d_i}{n} = \frac{D}{n}$$



Control Chart Development

$$UCL = \bar{u} + 3\hat{\sigma}_u$$

$$CL = \bar{u}$$

$$LCL = \bar{u} - 3\hat{\sigma}_u$$

$$\bar{u} = 100\bar{u}_A + 50\bar{u}_B + 10\bar{u}_C + \bar{u}_D$$

$$\hat{\sigma}_u = \left[\frac{(100)^2 \bar{u}_A + (50)^2 \bar{u}_B + (10)^2 \bar{u}_C + \bar{u}_D}{n} \right]^{1/2}$$



Low Defect Levels

- When defect levels or count rates in a process become very low, say under 1000 occurrences per million, then there are long periods of time between the occurrence of a nonconforming unit.
- Zero defects occur.
- Control charts (u and c) with statistic consistently plotting at zero are uninformative.
- Alternative is to chart the time between successive occurrences of the counts – or time between events control charts.
- If defects or counts occur according to a Poisson distribution, then the time between counts occur according to an exponential distribution.



Choice Between Attributes and Variables Control Charts

- Each has its own advantages and disadvantages
- Attributes
 - Data is easy to collect and several characteristics may be collected per unit.
 - Attributes control charts will not react unless the process has already changed (more nonconforming items may be produced).
- Variables
 - Data can be more informative since specific information about the process mean and variance is obtained directly.
 - Variables control charts provide an indication of impending trouble (corrective action may be taken *before* any defectives are produced).



Guidelines for Implementing Control Charts

1. Determine *which* process characteristics to control.
2. Determine *where* the charts should be implemented in the process.
3. Choose the proper *type* of control chart.
4. Take action to *improve* processes as the result of SPC/control chart analysis.
5. Select data-collection systems and computer software.

