




	9 0166042 COMMA SEL 5 010 12260 Plant 1 10 01648 72 MEDICOMMA 6 01642 50 PM
Hazards III	SAFETY 1- Feeling dizes 2- Non concentrations 3-Non behavious 4- Dropping of Fools of Henry dayies
Precautions While Working الإجراءات الرقائية	1-Wearing the required coat. 2-Wearing from drapping the Measuring device.
Required personal protective devices العدد الرقائية	Nothing required 2


















Required Row Materials - plates that we need to shaping it I metal - wood .] Required Machines & Tools 1- Lathe Machine [Turning Machine] 2 Milling machine 3 - shapping Machine 4- Grinding machine Procedures خطوات تنقيذ العمل Procedures I - Determine & install the piece on machine 2 - Determine Ratation speal 3- 11 culting depth - leed speed 5- casting liquid matter on machine to decrease





Scanned by CamScanner













School of Engineering Industrial Department Workshop Technology (Practical Exercise Sheet) المشغل Hard BAN الوقت الازم التعرين الماروا عاد 3/3/2 اسم العدرب باء المجموعة 0 10 11 SAFETY Hazards المخاطر المحتملة wintship Precautions While Working الإجراءات الوقلية 242 Dweared the righ comb Huncls From Rings Required personal protective devices went the suitable المداورالية


Scanned by CamScanner



Scanned by CamScanner




Scanned by CamScanner




School of Engineering
Industrial Department
Workshop Technology
(Practical Exercise Sheet)

	(F	Practical Exer	cise Sheet)		
Carpentry 5	المشغل ال	D	المجموعة	10	الشعبة
1:30 1:30	الوقت اللازم للن	أتدابوليلى	امنم المدرب	29/3/2018	التاريخ
	8 01654	141 -	4 رقا أمين و		اسماء المجم
100	9 016487	الدرامد 72	016 کود الرحنی خ	5776)gazo =	ו ו אוויים ב
	10 016425		6 مشرى حسو		2 السل ك
	11 016604	12 9	7 016 علاء الصف	القراقزة	06 100
				9,5	
		SAFE		1100	
Hazards المخاطر المحتملة	2- Iny	g in the	lingers. to wood 9.1 upment on H	om s	
Precautions While Working الإجراءات الرقائية	2- PLANS	Ting suita	ller's to pul ble lighting coat and by goggle	l shoes	oets
Required personal protective devices العدد الوقائية	3 glou	Aid Kit			




Scanned by CamScanner

Required Row Materials المواد اللازمة للعمل
1 suitable useed
2- Shilable Lables Por Work
2 - 3x110-2 - 1xc-1
Required Machines & Tools المكانن والعد المطلوبة
1- Hand Faw 12 12 8- Motof Rules
2 - Right anyle tool 3 9- Fixed Hammer
3. sole file 10- Vise
4- Cookse Bile
5- Trougle Pile
6-Chiel
7 - 11 minuse
Procedures خطوات تنفيذ العمل
1-Bling two pieces of wood [20cm long] 2- Select astraight line at adistance 2.6 cm from the Lip of
2- solect astraight time at the select region 103
4- place the piece on the vise and use the hand sown and
4- place the piece on the
1 - palish the selected part
1 5- Remove excess parts using the Fixed Hammer.
6- using the Piles to get suitable shape
6 19: 3- · · · · · · · · · · · · · · · · · ·
Scanned by CamScanner






Scanned by CamScanner



Scanned by CamScanner



Scanned by CamScanner

